

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established

DIAGRAM

T12S
R31E R32E
S 1/16
S 24 | S 19

Description of corner evidence found:

NONE

Description of monument and accessories I established to perpetuate the

original location of this corner: At corner position, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 18 inches in the ground, from which:

New BTs

A 11 inch diameter double bole Juniper bears South 46° East, 170.7 feet marked S1/16 S19 BT

A 12 inch diameter Juniper bears North 25° West, 34.5 feet marked S1/16 S24 BT

Raised mound of stone around new monument

Attached 54-9 signs and bearing tree tags to and painted a 6 inch red band around all bearing trees

Set steel fence posts approximately 5 feet South with 54-2 sign and approximately 5 feet East with 54-9 and 54-2 signs

Corner set October 21, 1983

Witnesses: Greg Blackman and Rick Robinson

See survey number 792

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1954
DUANE I. GRIFFITH
644

T12S
R31E R32E
S 1/16
S 24 | S 19
1983
OPLS 644

I used a steel tape and magnetic compass in the establishment of these accessories. I used 17½° East magnetic declination, and the distances to the new BTs are to the center of the tree. I attached a brass washer marked OPLS 644 by the BT blaze of the new BTs

Office of... Surveyor County of... Grant
State of... Oregon , I hereby certify that the within instrument was filed in this office
for record on the... 30 day of... NOV , 19... 83
Robert D. Bayliss by
(COUNTY OFFICIAL) (DEPUTY)