

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established by John B. David, under GLO contract number 131, dated June 8, 1869.

Surveyor General record states:

Set stone 15x9x8 for 1/4 Sec corner

DIAGRAM

T12S R32E

S 19

1/4

S 30

Description of corner evidence found:

NONE

The corner search area falls on a log landing. The entire area has been smoothed for logging operations.

Description of monument and accessories I established to perpetuate the

original location of this corner: At proportionate distance, I set a 2 1/2" x 30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which:

New BTs

A 10 inch diameter tamarack bears North 18° East, 141.1 feet, marked 1/4 S19 BT

A 8 inch diameter tamarack bears South 77° West, 95.5 feet, marked 1/4 S30 BT

Raised mound of stone around new monument



Set steel fence post approximately 5 feet East with 54-4 sign

Attached 54-4 signs and bearing tree tags to and painted a 6 inch red band around all bearing trees

Corner set October 21, 1983

Witnesses: Greg Blackman and Rick Robinson

See survey number 792



I used a steel tape and magnetic compass in the establishment of these accessories. I used 17 1/2° East magnetic declination, and the distances to the new BTs are to the center of the tree. I attached a brass washer marked OPLS 644 by the BT blaze of the new bearing trees.

Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 20 day of Nov, 1983
Robert D. Smith by _____
 (COUNTY OFFICIAL) (DEPUTY)