


CORNER RESTORATION

E 1/16 cor. between
CORNER Secs. 19&30 TWP 12 S. RANGE 32 E.

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:

No record of this 1/16 corner being established

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
J. L. Meyerholz

Aug. 8, 1984

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

EVIDENCE FOUND:

None

RECEIVED AND
FILED

SEP 25 1984

OFFICE OF COUNTY SURVEYOR

Robert D. Bagett
Attest: *Ann Marie Lawrence*

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point:

Set a 1½"x30" galvanized iron pipe 28 inches in the ground with brass cap marked as shown, from which I scribe NEW BEARING TREES:

A pine 12 ins. diam., bears N. 50° E., 75.4 ft., mkd. E 1/16 S19 BT.

A d. fir, 12 ins. diam., bears S. 42° E., 32.0 ft., mkd. E 1/16 S30 BT.

Used magnetic compass with 20° E. variation and steel tape measuring to head of a 40 d nail driven flush with BT blaze at root crown.

Surrounded pipe with a mound of stone to top of cap.

See Record Map of Survey No. 829

MONUMENT MARKED

