

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established by John B. David, under GLO contract number 131, dated June 8, 1869.

Surveyor General record states:

Set stone 17x9x6 for $\frac{1}{4}$ Sec corner

DIAGRAM

T12S R32E

S 21

$\frac{1}{4}$

S 28

Description of corner evidence found:

Found marked stone of called size in mound of stone

Description of monument and accessories I established to perpetuate the

original location of this corner: In place of stone, I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 21 inches in the ground from which:

New BTs

A 12 inch diameter P.Pine bears South 45° East, 35.5 feet, marked $\frac{1}{4}$ S28 BT
A 22 inch diameter P.Pine bears North 5° West, 17.3 feet, marked $\frac{1}{4}$ S21 BT

Buried the original stone South and alongside of the new monument

Raised mound of stone around new monument


Set steel fence posts approximately 5 feet West with 54-2 sign

and approximately 5 feet East with 54-2 and 54-4 signs attached

Attached 54-4 signs and bearing tree tags to and painted a 6 inch red band around all bearing trees

Corner set October 3, 1983

See survey number 792



I used a steel tape and magnetic compass in the establishment of these accessories. I used $17\frac{1}{2}^{\circ}$ East magnetic declination, and the distances to the new BTs are to the center of the tree. I attached a brass washer marked OPLS 644 by the BT blaze of the new bearing trees.

T12S R32E

S 21

$\frac{1}{4}$

S 28

1983

OPLS 644

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*30* day of.....*Nov*....., 19..*83*
.....*Robert D. Byrd*..... by
(COUNTY OFFICIAL) (DEPUTY)