


History of original corner establishment:
Corner established in 1869 by John B. David under
General Land Office Contract No. 131.
Surveyor General Record states;
Set stone 16" x 14" x 8" for 1/4 section corner.



No record of subsequent remonumentation was found in County records.
Description of corner evidence found:

Found marked stone 16" x 15" x 6" in mound of stone.

See map of survey dated September, 1980.
Description of monument and accessories I established to perpetuate the
original location of this corner:

In place of stone I set 2 1/2" x 30" aluminum monument marked as shown 29" in ground
from which;



NEW BTs

A 9" p pine bears N 67° E, 26.7 ft marked 1/4 S24 BT

A 12" p pine bears S 12° W, 42.3 ft marked 1/4 S25 BT

Buried stone east and alongside

Raised mound of stone



Brass washer nailed to BT blaze.
Used steel tape and magnetic compass
with 15° East declination.
Measured to center of new B.T.s

Office of... Surveyor ... County of... Grant ...
State of... Oregon ... I hereby certify that the within instrument was filed in this office
for record on the... 31 day of... Oct ... 1980...
Robert D. Bayne by ...
(COUNTY OFFICIAL) (DEPUTY)