

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. A-16

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T11S R33E
S34
E1/16--
S3
T12S
1986
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 22" in the ground and placed a ring of stone filled with earth around the pipe.

From Which:

A Fir 6" dia., Bears N81°W., 7.1 ft., scribed: E1/16 S34 BT

A Fir 8" dia., Bears S27°E., 57.5 ft., scribed: E1/16 S3 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, South & East 5 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1983
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: July 15, 1986
Refer to Map of Survey No. 949

Office of..... *Surveyor* County of..... *Grant*
State of..... *Oregon* I hereby certify that the within instrument was filed in this office
for record on the..... *24* day of..... *Oct* , 19*86*.....
..... *Robert W. Baggett* by
(COUNTY OFFICIAL) (DEPUTY)