


History of original corner establishment:

Corner established in 1881 by Robb and Gradon under General Land Office Contract No. 383.
Surveyor General Record states;

Set stone 14 x 10 x 6 in stone mound for corner to section 5,6,7, and 8 from which;

A tamarack 16" diameter bears N 30° E, 29 links dist.

A pine 14" diameter bears N 55° W, 68 links dist.



No record of subsequent remonumentation was found in county records.
Description of corner evidence found:

Found marked stone call size in mound of stone and both BTs.

See map of survey dated September, 1980.
Description of monument and accessories established to perpetuate the original location of this corner:

In place of stone I set 2 1/2" x 30" aluminum monuments marked as shown 27" in ground from which;

ORIGINAL BTs

A 13" tamarack stump bears N 50° E, 19.2 ft to face of blaze, scribes visible

A 20" p pine bears N 55° W, 46.3 ft to face of blaze, live vigorous, scribes visible

NEW BTs


A 32" p pine bears N 35° E, 65.1 ft marked T12S R33E S5 BT

A 8" fir bears S 89° W, 14.6 ft marked T12S R33E S7 BT

A 12" fir bears S 140° E, 39.4 ft marked T12S R33E S8 BT

Buried stone east and along side

Raised mound of stone



Brass washer nailed to BT blaze.
Used steel tape and magnetic compass with 15° East declination.
Measured to center of new B.T.s

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*..... I hereby certify that the within instrument was filed in this office
for record on the.....*31*..... day of.....*Oct*....., 19.....*80*.....
.....*Robert A. Baggett*..... by.....
(COUNTY OFFICIAL) (DEPUTY)