


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1869 by John B. David under General Land Office Contract No. 131. Surveyor General Record states;

Set stone 18" x 9" x 8" for $\frac{1}{4}$ section corner.

Remonumented at proportionate distance in 1966 by BLM in unrecorded survey by Lynn M. Roseberry.



Description of corner evidence found:

Brass cap and BTs

See map of survey dated September, 1980.

Description of monument and accessories I established to perpetuate the original location of this corner:

none


This information is copied from BLM field notes for public record.

Set an iron post, 28" long $2\frac{1}{2}$ " diameter, 24" in the ground with brass cap marked from which;

A larch, 17" diameter bears N $15\frac{1}{2}^{\circ}$ E, 67 links dist. marked $\frac{1}{4}$ S17 BT

A fir, 23" diameter bears N 33° W, 70 links dist. marked $\frac{1}{4}$ S18 BT

Descend 30' over NE slope.



Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 31 day of Oct, 1980
Robert L. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)