

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. T-3

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T12S R33E
C 1/4
S30
1989
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 10" in the ground and raised a mound of stone around the pipe.

From Which:

A Ponderosa Pine 10" dia., Bears S11⁰W., 24.0 ft., scribed: C1/4 S30 BT

A Ponderosa Pine 10" dia., Bears S75⁰W., 40.6 ft., scribed: C1/4 S30 BT

Measurements to trees taken with metal tape and magnetic compass with 20⁰ East declination set off.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set a steel fence posts with warning & Boundary Signs, alongside monument.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1859
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.

On: April 17, 1989

Refer to Map of Survey No. 1075

Witnesses: D. Mitchell Ferguson & Ken Delano

Office of SURVEYOR County of GRANT
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 21 day of MAR, 1990
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)