


CORNER RESTORATION

CORNER: S1/16 Cor. Sec. 35 Twp. 12 S. Range 33 E., W.M.

ORIGINAL SURVEY BY: CORNER NOT

CONTRACT NUMBER: PREVIOUSLY

CONTRACT DATE: ESTABLISHED




ORIGINAL DESCRIPTION: NONE, (Corner not previously established)


RESTORATION BY, STAMP AND DATE:

Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

MAR 21 2011

BY: 



EXPIRES: 6/30/2012

March 18, 2011

EVIDENCE FOUND: NONE, (Corner not previously established)

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

At the corner point: I set a 5/8" X 30" iron pin with attached 2" aluminum cap marked as shown below. Set pin 29" in the ground and built a 2 foot mound of stone.

From which, I SET NEW REFERENCE POINTS:

A 5/8"x30" iron pin, bears S45°52'W, 45.36 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING"

A 5/8"x30" iron pin, bears N41°53'W, 43.59 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING"

See Record Map of Survey No. 1920, filed in the office of the Grant County Surveyor for Basis of Bearings.

