

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner established by John B. David under General Land Office Contract No. 131, dated June 8, 1869.

Surveyor Generals' Records state:

Set stone 18"x12"x9" for 1/4 sec. corner.

Note: no restoration appears in County records.



Description of corner evidence found:

No evidence found- lost and reestablishment by single proportion. Corner falls on east side of skid trail in second growth fir and pine thicked on north slope. Area has been logged several times with much ground disturbance.

Description of monument and accessories established to perpetuate the original location of this corner:

At single proportionate location, I set a 30 inch long 2 1/2 inch dia. aluminum pipe 26 inches in ground, with 3 1/4 inch alum. cap marked:

Marked New Bearing Trees;

A douglas fir, 13" DBH, bears South 70° East, 22.8 feet, scribed "1/4 S20 BT" with brass washer "LS 1026";

A douglas fir, 9" DBH, bears South 16° West, 4.1 feet, scribed "1/4 S20 BT" with brass washer "LS 1026".

Brass washers nailed in lower blaze.

Raised stone mound 2 ft. dia. Placed signs 54-3 and 54-4 and painted red band and faces on BT's. Set steel posts with sign 54-4 north of corner.

I hereby certify the above corner monument was re-established as herein described on June 15, 1981.

Witnesses: William S. DeGroot
William S. DeGroot, LS 1633

Shelby H. Griggs
Shelby H. Griggs, Chainman



REGISTERED PROFESSIONAL LAND SURVEYOR

David B. Armstrong

8/17/81 OREGON
AUGUST 22, 1975
DAVID B. ARMSTRONG
1026

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 29 day of August, 1981
Robert D. Begett by _____
(COUNTY OFFICIAL) (DEPUTY)