


CORNER RESTORATION

N1/16 Between Secs.
CORNER 16 & 17 TWP 12 S. RANGE 35 E. W.M.

ORIGINAL SURVEY BY: BAMFORD ROBB
CONTRACT NUMBER: 383
CONTRACT DATE: March 26, 1881



ORIGINAL DESCRIPTION:

Corner not previously established of record.

I established this 1/16 corner at midpoint and on line between the NW Sec. corner and the W $\frac{1}{4}$ corner of Sec. 16.

RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
F. Jackson
K. Leckenby

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

June 9, 1979

Grant County Surveyor.

JUL 2 1979
John Liveira
JOHN LIVEIRA, County Clerk
By _____ Deputy

EVIDENCE FOUND:

See Map of Survey No. 570.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED: Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set 5/8"x30" iron pin in a mound of stone, from which I scribe NEW BEARING TREES:

A 3" tamarack bears N. 82° W., 9.4 ft. mkd. XCSBT.
A 3" fir bears N. 55 °E., 13.7 ft. mkd. XCSBT.

I used a compass with a 20° East variation and steel tape, measuring to the face of the blaze on the bearing trees.

MONUMENT MARKED

