


CORNER RESTORATION

C $\frac{1}{4}$ Cor.
CORNER Sec. 16 TWP 12 S. RANGE 35 E., W.M.

ORIGINAL SURVEY BY: BAMFORD ROBB

CONTRACT NUMBER: 383

CONTRACT DATE: March 26, 1881



ORIGINAL DESCRIPTION:

Corner not previously established of record. I established the center $\frac{1}{4}$ corner at the intersection of lines from opposite corresponding $\frac{1}{4}$ corners of the section.

RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
F. Jackson
K. Leckenby

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

JUL 2 1979
John Liveira
JOHN LIVEIRA, County Clerk
By _____ Deputy

June 9, 1979

Grant County Surveyor.

EVIDENCE FOUND:

See Map of Survey No. 570.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set 5/8"x30" iron pin in mound of stone, from which I scribe NEW BEARING TREES:

A 6" lodgepole bears S. 34° E., 55.6 ft. mkd. C $\frac{1}{4}$ S16CSBT.
An 11" lodgepole bears S. 72° W., 65.6 ft. mkd. C $\frac{1}{4}$ S16CSBT.

I used a compass with a 20° East variation and steel tape, measuring to the face of the blaze on bearing trees.
Surrounded pin with mound of stone.

MONUMENT MARKED

