


CORNER RESTORATION

CE1/16 Cor.
CORNER Sec. 16 TWP 12 S., RANGE 35 E., W.M.

ORIGINAL SURVEY BY: BAMFORD ROBB

CONTRACT NUMBER: 383

CONTRACT DATE: March 26, 1881



ORIGINAL DESCRIPTION:

Corner not previously established of record.

I established this 1/16 corner at midpoint and on line between the
E $\frac{1}{4}$ corner and the center $\frac{1}{4}$ corner of Sec. 16.

RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
F. Jackson
K. Leckenby

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

JUL 2 1979
John Liveira
JOHN LIVEIRA, County Clerk
By.....Deputy

June 9, 1979

Grant County Surveyor.

EVIDENCE FOUND:

See Map of Survey No. 570.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set 5/8"x30" iron pin in mound of
stone, from which I scribe NEW BEARING TREES:

A 13" P. Pine bears N. 55° E., 29.0 ft. mkd. CE1/16S16CSBT.
A 23" P. Pine bears N. 12° W., 14.2 ft. mkd. CE1/16S16CSBT.

I used true bearings and steel tape, measuring to the
face of the blaze on the bearing trees.

MONUMENT MARKED

