


CORNER RESTORATION

E 1/4 Corner
CORNER Sec. 16 TWP 12 S RANGE 35 E., W.M.
ORIGINAL SURVEY BY: BAMFORD ROBB
CONTRACT NUMBER: 383
CONTRACT DATE: March 26, 1881



ORIGINAL DESCRIPTION:
North between Secs. 15 & 16:
40.00 set basalt stone 18x8x7 in mound of stone for 1/4 sec. cor. from which:
A pine 28" in diam. bears S. 52° W., 31 lks. dist.

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
F. Jackson
K. Leckenby



May 31, 1979 Grant County Surveyor.

EVIDENCE FOUND:

Found the original corner stone a 19"x7"x6" basalt stone set in mound of stone, marked 1/4 on the West face, from which:

ORIGINAL BEARING TREE:
A 34" pine bears S. 84° W., 22.0 ft. mkd. 1/4 S

See Map of Survey No. 570.


DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

I accept the position of the corner stone.
At the corner point: Set 1 1/2"x30" iron pipe 24" in ground with brass cap marked as shown, from which I scribe
NEW BEARING TREE:

A 12" fir bears N. 16° E., 15.4 ft. mkd. T12SR35E 1/4 S15CSBT

I buried the original corner stone South and alongside the iron pipe and surrounded the pipe with a mound of stone. I used a compass with 20° East variation and steel tape, measuring to the center of the bearing trees.

MONUMENT MARKED



RECEIVED AND
FILED

JUL 2 1979
John Liveira
JOHN LIVEIRA, County Clerk

By Deputy