


CORNER RESTORATION

CS1/16 cor.
CORNER Sec. 16 TWP 12 S. RANGE 35 E., W.M.
ORIGINAL SURVEY BY: BAMFORD ROBB
CONTRACT NUMBER: 383
CONTRACT DATE: MARCH 26, 1881



ORIGINAL DESCRIPTION:

Corner not previously established of record. I established this 1/16 corner at the midpoint and on a line between the S $\frac{1}{4}$ corner and the center $\frac{1}{4}$ corner of Section 16.

RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE.

R. D. Bagett
F. Jackson
K. Leckenby

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

JUL 24 1979
John Liveira
JOHN LIVEIRA, County Clerk
By, ... Deputy

June 9, 1979

Grant County Surveyor.

EVIDENCE FOUND:

See Map of Survey No. 570.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED: Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set 5/8"x30" iron pin in a mound of stone, from which I scribe NEW BEARING TREES:
A 4" tamarack bears S. 64° W., 7.6 ft. mkd.
CS1/16S16CSBT.
A 4" fir bears N. 71° W., 8.1 ft. mkd.
CS1/16S16CSBT.

I used true bearings and steel tape, measuring to the face of the blaze on the bearing trees.

MONUMENT MARKED

