


CORNER RESTORATION

CORNER S¹/₄ corner Sec. 16 TWP 12 S. RANGE 35 E., W.M.

ORIGINAL SURVEY BY: BAMFORD ROBB

CONTRACT NUMBER: 383

CONTRACT DATE: March 26, 1881



ORIGINAL DESCRIPTION:

S. 89° 49' W., on true line between Secs. 16 & 21:

40.06 set basalt stone 18x6x5 in mound of stone for $\frac{1}{4}$ sec. cor. from which a tamarack 6" in diam. bears N. 25° E., 14 lks. dist.

RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
F. Jackson
K. Leckenby

REGISTERED
PROFESSIONAL
LAND SURVEYOR

JUL 2 1979
John Liveira
JOHN LIVEIRA, County Clerk
By _____ Deputy

Robert D. Bagett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

June 9, 1979

Grant County Surveyor.

EVIDENCE FOUND:

No evidence of original $\frac{1}{4}$ corner was found.

After a diligent search for corner evidence with no luck, I set the corner at single proportionate distance between the found section corners at the S.W. & S.E. corners of the section.

See Map of Survey No. 570.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED: Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set 1 $\frac{1}{2}$ "x30" iron pipe 25" in the ground with brass cap marked as shown: from which I scribe NEW BEARING TREES:

A 12" fir bears S. 49° W., 31.6 ft. mkd. T12SR35E $\frac{1}{4}$ S21CSBT
A 7" fir bears N. 6° W., 45.3 ft. mkd. T12SR35E $\frac{1}{4}$ S16CSBT.

I used a compass with 20° East variation and steep tape, measuring to the center of the bearing trees.
Surrounded pipe with mound of stone.

MONUMENT MARKED

