CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. A-11

History of original corner establishment:
Corner 1s originally established by Robb & Gradon, in 1881, under "General Land Office" Contract No. 383. Surveyor Generals Notes State:
Set post for 1/4 Sec. Cor

from which

A fir 26 in. dia., bears S10°W., 8 lks dist.
" Tamarack 10 in. dia., bears N20°W., 22 lks dist.

DIAGRAM
T11S R33E
S33
1/4-.-
S4
T12S
1986
PLS 848

In 1959, Howard Taylor, perpetuated the corner, by setting a stone at record measure from the remains of the original bearing trees, and scribing new bearing trees. Martin Louther found the work as performed by Taylor and the remains of the original bearing trees, in 1959.

Description of corner evidence found:
Found 15"x11"x8" stone, set firmly in the ground as established by Howard Taylor, from record measure from the remains of the original bearing trees.
Taylor was able to identify original trees in 1959.
Found trees as scribed by Taylor, as follows:
A Fir 14" dia., Bears S58°W., 21.4 ft., with scribing visible.
A Tamarack 16" dia., Bears N80°E., 14.9 ft.,with 1/4 BT visible.
Since I have found Howard Taylor perpetuation of Corners to be reliable, I accepted the above described stone as the 1/4 Sec. Cor. even though I could not identify any original evidence. The evidence as perpetuated by Taylor is also confirmed by Martin Louther, who I have found to be reliable in identifying original evidence.

Description of monument and accessories I established to perpetuate the original location of this corner:
Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 24" in the ground.
From Which.
A Fir 6" dia., Bears S73°E., 26.7 ft., scribed: 1/4 S4 BT
A Fir 8" dia., Bears N62°E., 9.0 ft., scribed: 1/4 S33 BT
Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.
Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, East & West 5 ft. from the corner.

REGISTERED PROFESSIONAL LAND SURVEYOR
OREGON
JULY 12, 1960
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt.Vernon Oregon.
On: July 29,1986
Refer to Map of Survey No. 949

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 24 day of Oct, 1986
Robert D. Smith by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

GPO—798-275

A-11