CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. U-3

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T12S R33E
C
S1/16|S30
C
1989
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 10" in the ground and raised a mound of stone around the pipe.
From Which:
A Juniper 14" dia., Bears N55°W.,62.3 ft., scribed: C-S 1/16 S30 BT
A Ponderosa Pine 10" dia., Bears S 9°E.,52.8 ft., scribed: C-S 1/16 S30 BT
Measurements to trees taken with metal tape and magnetic compass with 20° East declination set off.
Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning sign, North 3 ft. from the corner.

REGISTERED PROFESSIONAL LAND SURVEYOR
OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt.Vernon Oregon.
On: April 17, 1989
Refer to Map of Survey No. 1075
Witnesses: D.Mitchell Ferguson & Ken Delano

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 21 day of MAR, 1990
Robert D Rogers by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

U-3