

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. X-17

History of original corner establishment:

This corner was originally established by Levi L. Walker, in 1880, under GLO Contract No. 374. Surveyor General Field Notes state:

Set for 1/4 Section corner a basalt stone 12x7x6 and raised stone mound.

DIAGRAM
T13S R27E
1/4
S34|S35
1993
PLS 2405

Description of Corner Evidence Found:

Searched for not found. The search area was on a moderately steep slope, but I could find no evidence of the stone or mound.

Re-established by single proportionate measure

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 26" in the ground.

From Which:

White Fir, 10" dia., bears N54°00'W, 7.4 ft., scribed: 1/4 S34 BT
Ponderosa Pine, 10" dia., bears N17°27'E, 23.2 ft., scribed: 1/4 S35 BT
White Fir, 12" dia., bears S79°53'E, 20.7 ft., scribed: 1/4 S35 BT
Douglas Fir, 16" dia., bears S05°59'W, 69.4 ft., scribed: 1/4 S34 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) sign 5' north of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 26, 1989
SUSAN E. NEWSTETTER
2405

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: Rick Saul, Brad
Cates and D. Mitchell Ferguson
August 4, 1993
Refer to Grant Co. Survey No.:1279

Office of Surveyor County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 2 day of Jan, 1994
Robert D. Beyer by _____
(COUNTY OFFICIAL) (DEPUTY)

X-17