

CORNER RESTORATION T135


R27E 1/6 R28E

CORNER S 1/6 12/7 TWP 135 RANGE 27E 28E

ORIGINAL SURVEY BY: Corner not previously established.

CONTRACT NUMBER:

CONTRACT DATE:



ORIGINAL DESCRIPTION:

Corner not previously established

RESTORATION BY, STAMP AND DATE:

April 1982



EVIDENCE FOUND:

N. A.

RECEIVED AND
FILED

APR 21 1982

OFFICE OF COUNTY SURVEYOR


Robert D. Baggett
Attest: Lammie Lawrence

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2 1/2" x 30" galv. iron pipe
with 3" Brass cap, stamped as
shown & Raised a mound of stone
around the pipe

MONUMENT MARKED



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

H-1