

CORNER RESTORATION

T 135


R 27E R 28E

CORNER 7, 12, 13 & 18 TWP 13 S. RANGE 27 & 28 E

ORIGINAL SURVEY BY: W. Byars.

CONTRACT NUMBER: 185

CONTRACT DATE: 1873






ORIGINAL DESCRIPTION:

Set corner to Secs. 7, 12, 13 & 18, A stone
18 x 12 x 4

RESTORATION BY, STAMP AND DATE:

April 1982



EVIDENCE FOUND:

John Day River has destroyed all evidence
Set cor. by proportion along the Range line
from 1/4 cor. 1/2 mi North & 1 1/2 mi South.

**RECEIVED AND
FILED**

APR 2 1 1982

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED

Show how trees are scribed and basis of bearings, including compass var.

OFFICIAL COUNTY SURVEYOR

Robert D. Segott
Attest: Sammie Lawrence

MONUMENT MARKED

Set 2 1/2" x 30" galv. iron pipe with 3"
Brass cap, stamped as shown, set 20"
in the ground & placed a mound of
stone around the pipe, John Day Riv.
approx. 20 ft. North.

Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

