

CORNER RESTORATION T135

R27E R28E
13 18


24 19

CORNER $\frac{1}{4}$ 24 & 19 TWP 135 RANGE 27 & 28 E

ORIGINAL SURVEY BY: W. Byars

CONTRACT NUMBER: 185

CONTRACT DATE: 1873





ORIGINAL DESCRIPTION:

38.50 ch. A Dry Ravine C-NE

40.00 ch Set $\frac{1}{4}$ Sec. Cor., A Stone 13 x 9 x 7

RESTORATION BY, STAMP AND DATE:

April, 1982



RECEIVED AND
FILED

APR 21 1982

OFFICE OF COUNTY SURVEYOR

Robert D. Baggett
Attest: Lennie Lawrence

EVIDENCE FOUND:


At 1.50 ch, south of a dry ravine, found a 13 x 9 x 7 stone, with $\frac{1}{4}$ visible, set nearly flush with the ground. Accepted center of stone as $\frac{1}{4}$ cor. position.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2 $\frac{1}{2}$ " x 30" galv. iron pipe with 3" Brass cap stamped as shown, set 20" in the ground, placed orig. stone south alongside pipe.

MONUMENT MARKED



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820