


CORNER RESTORATION

CORNER E 1/4 Sec. 21 TWP 13 S RANGE 28E

ORIGINAL SURVEY BY: Wm. Byars

CONTRACT NUMBER: 197

CONTRACT DATE: July 14, 1873





ORIGINAL DESCRIPTION:

North on true line between Sections 21 & 22

40.00 set basalt stone 12x10x6 for the quarter section corner.

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
G. L. Earl



June 9, 1980

Grant County Surveyor.

EVIDENCE FOUND:

At East 1/4 cor. Sec. 21:

Found basalt stone 12x11x6 inches marked 1/4 on West face and firmly set in a mound of stone.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set a 1 1/2"x30" galvanized iron pipe 16 inches in the ground with brass cap marked as shown.

From which I scribe NEW BEARING TREES:

A Juniper 10 inches in diameter bears N. 43° E., 96.6 ft., marked 1/4 S22 CSBT.


A Juniper 13 inches in diameter bears N. 6° W., 86.2 ft., marked 1/4 S21 CSBT.

I buried the original corner stone South and alongside the iron pipe, and raised a mound of stone, 3 ft. base to top of pipe.

Used compass with 20° E. variation and steel tape, measuring to face of BT Blaze.

See Map of Survey No. 617.

MONUMENT MARKED



RECEIVED AND
FILED

JUN 13 1980

OFFICE OF COUNTY SURVEYOR

Robert D. Bagett
Robert D. Bagett