


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: ORIGINAL CORNER SET BY W.H. BYARS UNDER CONTRACT NO. 185 DATED MAY 7, 1873. HIS NOTES STATE: SET CORNER TO SECTIONS 3, 4, 33 & 34, A STONE 22x12x6 RESURVEYED BY G.L.O. IN 1939. 1939 NOTES STATE:



THE ORIGINAL CORNER OF SECS. 33 + 34 ONLY, WHICH IS A BASALT STONE 21x9x9 INS., FIRMLY SET, WITH 3 GROOVES ON E. FACE. AT POINT FOUR CORNER SET AN IRON POST, 3 FT. LONG, 2 INS. DIAM., 28 INS. IN GROUND, WITH BRASS CAP MKD (AS SHOWN BELOW) FROM WHICH A YELLOW PINE 10 INS. DIAM. BEARS N 15 1/2° E 213 LKS. DIST. MKD. T13S R28E S34 BT A YELLOW PINE 15 INS. DIAM. BEARS N 5° W 125 LKS. DIST. MKD. T13S R28E S33 BT

Description of corner evidence found:

2" PIPE LYING ON GROUND WITH G.L.O. BR. CAP MKD → APPARENTLY WAS DUG UP BY CAT WORK IN AREA. STONE MOUND MISSING.

T13S R28E
S33 | S34
T14S R28E
S3
1939

FOUND BOTH 1939 BT'S IN GOOD CONDITION AS FOLLOWS:

A 20" D.B.H. P. PINE, GOOD SCAR, BEARS N 15 1/2° E, 140.6 FT. (213 LKS.)
A 21" D.B.H. P. PINE, GOOD SCAR, BEARS N 5° W 82.5 FT. (125 LKS.)

Description of monument and accessories I established to perpetuate the original location of this corner:

I RE-SET THE FOUND 2" PIPE WITH G.L.O. BR. CAP MKD. AS SHOWN ABOVE, TO MATCH RECORD CALLS TO FOUND 1939 BT'S AS SHOWN ABOVE. ALSO MATCHES CALL TO DRY WASH LYING 190 CH. EAST OF CORNER AS PER 1939 NOTES.

SET STEEL POST 3' W. OF CORNER, W/SIGNS 54-2 + 54-4

DATE: 7-19-82

WORK DONE BY: VICTOR McLIND

WITNESS: D. WRIGHT

L. McLIND.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Victor M. McLind

OREGON
JULY 17, 1870
VICTOR M. McLIND
934

Office of *Surveyor* County of *Grant*
State of *Oregon*, I hereby certify that the within instrument was filed in this office
for record on the *20* day of *April*, 19*82*.
Victor M. McLind by *D. Wright*
(COUNTY OFFICIAL) (DEPUTY)