


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T.13S., R.29E., INDEX L-02

History of original corner establishment:

This corner not previously established.



Description of corner evidence found:

Description of monument and accessories I establish to perpetuate the original location of this corner:

At the position determined by survey (See Grant County Survey No. ~~1710~~ ¹⁷¹¹), set a 2-1/2" x 30" aluminum pipe monument w/3" dia. cap stamped as shown in the DIAGRAM, 12" in the ground, raised a 4' dia. x 3' high mound of earth and stone, from which:

A 5/8"x30" Rebar Pin bears S72°45'W, 14.0 ft.

A 5/8"x30" Rebar Pin bears N39°30'E, 12.0 ft.

Placed a yellow plastic cap marked "FSE SURVEY MARKER" on both pins.

DIAGRAM

T13S R29E
W1/16
C---C
S18
2004
PLS 49865.


Measurements to accessories taken with a magnetic compass, declination 18° East, and distances measured with nylon clad steel tape.

I hereby certify that the above corner point was perpetuated as shown hereon on July 19, 2004

Witness: D. Mitchell Ferguson, LSIT
David H. Herburger, Surv. Tech.

Office of County Surveyor _____ County of Grant
State of Oregon. I hereby certify that the within instrument was filed in this office
for record on the 2 day of Sept., 2004

Robert D. Barger by _____
County Surveyor Deputy



RENEWAL DATE:
01/01/2006