


CORNER RESTORATION

CORNER: N1/4 SEC. 24, TWP. 13 S., RANGE 29 E.

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION: Set Stone 16x12x7 for 1/4 Sec. Corner

RESTORATION BY, STAMP AND DATE:

R.D. Bagett
D.E. Mooney
M.C. Springer

RECEIVED AND
FILED

NOV. 28, 2001
OFFICE OF COUNTY SURVEYOR
Robert D. Bagett

ATTEST: *Michael C. Springer*

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

Renewal Date 12/31/01

November 16, 2001

EVIDENCE FOUND: After a diligent search, I found no evidence of the original corner. I declare this corner lost and establish its position at single proportionate measure between the northwest and northeast corners of section 24.

See Record Map of Survey No. 1616

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings including compass var.

At the corner point: I set a 1½"x30" galv. iron pipe, 26" in the ground, with attached Bagett-Griffith and Blackman brass cap marked as shown.


From which I SET A NEW REFERENCE POINTS:

A 5/8"x30" iron pin, bears N45°E, 25.0 ft., with attached alum. cap marked BGB SURVEY MARKER
RP 1 2001

A 5/8"x30" iron pin, bears S45°E, 25.0 ft., with attached alum. cap marked BGB SURVEY MARKER
RP 2 2001

A 5/8"x30" iron pin, bears S45°W, 25.0 ft., with attached alum. cap marked BGB SURVEY MARKER
RP 3 2001

A 5/8"x30" iron pin, bears N45°W, 25.0 ft., with attached alum. cap marked BGB SURVEY MARKER
RP 4 2001



Raised a mound of stone 2 ft. base to top of cap. Used Leica SR530 RTK GPS receivers to measure reference points.