

JUN 1 1978
JOHN LIVEIRA, County Clerk

CORNER RESTORATION


By _____ **Deputy**

CORNER W 1/4 TWP 13 S RANGE 29 E

ORIGINAL SURVEY BY: JOHN B. DAVID

CONTRACT NUMBER: 131

CONTRACT DATE: JUNE 8, 1869



ORIGINAL DESCRIPTION:

South on West boundary of Sec. 19.

40.00 Set Stone 14 x 7 x 5 for 1/4 Sec. Corner.

RESTORATION BY, STAMP AND DATE:

OREGON EAST ENGINEERING, INC.
PO BOX 277
MT. VERNON, OREGON



EVIDENCE FOUND:

FOUND STONE 14 x 8 x 5 WITH A FAINTLY VISIBLE 1/4 SCRIBE IN A ROSETTE.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

SET A 2½" x 30" GALV. IRON PIPE, WITH BRASS CAP,
IN THE GROUND AND RAISED A MOUND OF STONE UP
AROUND THE MONUMENT. BURIED ORIGINAL STONE ALONG
SIDE OF PIPE. FROM WHICH:

A 16" JUNIPER BEARS N76 $\frac{1}{2}$ ° W - 26.2 FT.
SCRIBED 1/4 S 24 BT

A 12" JUNIPER BEARS N 86°E - 123.0 FT.
SCRIBED 1/4 S 19 BT

MONUMENT MARKED



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

COMPASS VARIATION ~~20~~ 20° E

P-1