


CORNER RESTORATION

CORNER SW 19 TWP 13 S RANGE 29 E
ORIGINAL SURVEY BY: JOHN B. DAVID
CONTRACT NUMBER: 131
CONTRACT DATE: JUNE 8, 1869



ORIGINAL DESCRIPTION:

South on West boundary of Sec. 19.
80.00 Set Stone 15 x 10 x 5 for corner to secs.
24, 25, 19 & 30.


RECEIVED AND
FILED

JUN 23 1978

JOHN LIVEIRA, County Clerk
By *Deputy* Deputy

RESTORATION BY, STAMP AND DATE:

OREGON EAST ENGINEERING, INC.
PO BOX 277
MT. VERNON, OREGON



EVIDENCE FOUND:

FOUND STONE 15 x 10 x 5 WITH NOTCHES VISIBLE IN A PARTIAL ROSETTE.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.
SET A 2½" x 30" GALV. IRON PIPE, WITH BRASS CAP, IN THE GROUND
AND RAISED A MOUND OF STONE UP AROUND THE MONUMENT. BURIED
ORIGINAL STONE ALONG EAST SIDE OF PIPE. FROM WHICH:
A 14" JUNIPER BEARS N 09°E - 51.4 FT.,
SCRIBED T13SR29ES19 BT

A 10" JUNIPER BEARS S 23°E - 176.7 FT.
SCRIBED T13SR29ES30 BT
A 16" JUNIPER BEARS S 67°W - 98.4 FT.
SCRIBED T13SR28ES25 BT

Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

COMPASS VARIATION 20°E

MONUMENT MARKED



R-1