


CORNER RESTORATION

CORNER S.W. Sec 20 TWP 13S RANGE 29E

ORIGINAL SURVEY BY: Thompson, Pengra, David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1809



ORIGINAL DESCRIPTION:

Set stone 17 x 10 x 6

Found in 1914 in recorded survey by Vernon Glaze

RESTORATION BY, STAMP AND DATE:



JULY 10, 1964
DUANE I. GRIFFITH
644

Nov 25 1969

EVIDENCE FOUND:

Mound of stone; no marked stone found.
Mound of stone in harmony with call on
Oregon State Highway Map No. 7B-20-5

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 1½" x 30" iron post with brass cap, 20" MONUMENT MARKED
in the ground.

No accessories available.

GRANT COUNTY SURVEYOR

T13S R29E

S-19 S-29

S-30 S-29
1969

LS 644

Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

R-5