


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T.13S., R.29E., INDEX R-11

History of original corner establishment:

This corner was originally established by John B. David under G.L.O. contract number 131, dated June 8, 1869. Survey General notes state:

Set Stone 17x8x7 for 1/4 Sec. Corner.



Description of corner evidence found:

No evidence of this corner recovered. Corner position falls near a residence.

Description of monument and accessories I establish to perpetuate the original location of this corner:

At proportionate measure(See Grant County Survey No. 1738), set a 2-1/2" x 30" aluminum pipe monument w/3" dia. cap stamped as shown in the DIAGRAM, 30" in the ground, from which:

- A 5/8"x30" Rebar Pin bears N12°W, 17.2 ft.
- A 5/8"x30" Rebar Pin bears N83°E, 18.4 ft.
- A 5/8"x30" Rebar Pin bears S45°E, 19.1 ft.
- A 5/8"x30" Rebar Pin bears S44°W, 18.1 ft.

Placed a yellow plastic cap marked "FS&E SURVEY MARKER" on all pins.

DIAGRAM

T13S R29E
S21
1/4 - -
S28
2005
PLS 49865

Measurements to accessories taken with a magnetic compass, declination 18° East, and distances measured with nylon clad steel tape.

I hereby certify that the above corner point was perpetuated as shown hereon on October 17, 2005

Witness: D. Mitchell Ferguson, LSIT
David H. Herburger, Surv. Tech.

Office of County Surveyor County of Grant
State of Oregon . I hereby certify that the within instrument was filed in this office
for record on the 25 day of Nov. , 2005

Robert D. Beyer by _____
County Surveyor Deputy

