


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T.13S., R.29E., INDEX T-09

History of original corner establishment:

This corner was originally established by John B. David under G.L.O. contract number 131, dated June 8, 1869. Survey General notes state:

Set Stone 14x10x7 for 1/4 Sec. Corner.



Description of corner evidence found:

This corner falls in a draw bottom with signs of periodic flash flooding. No evidence of this corner recovered.

Description of monument and accessories I establish to perpetuate the original location of this corner:

At proportionate measure(See Grant County Survey No. 1738), set a 2-1/2" x 30" aluminum pipe monument w/3" dia. cap stamped as shown in the DIAGRAM, 22" in the ground, from which:

- A 5/8"x30" Rebar Pin bears N44°W, 14.0 ft.
- A 5/8"x30" Rebar Pin bears N26°E, 9.0 ft.
- A 5/8"x30" Rebar Pin bears S47°E, 14.4 ft.
- A Juniper, 6" dia., bears S3°E, 37.8 ft., scribed 1/4 S28 BT

Placed a yellow plastic cap marked "FS&E SURVEY MARKER" on all pins.


DIAGRAM

T13S R29E
1/4
S29 | S28
2005
PLS 49865

Measurements to accessories taken with a magnetic compass, declination 18° East, and distances measured with nylon clad steel tape.

I hereby certify that the above corner point was perpetuated as shown hereon on March 1, 2005

Witness: D. Mitchell Ferguson, LSIT
David H. Herburger, Surv. Tech.



Office of County Surveyor County of Grant
State of Oregon. I hereby certify that the within instrument was filed in this office for record on the 25 day of Nov, 2005

Robert D. Sargent by Deputy
County Surveyor

RENEWAL DATE:
01/01/2006