

RECEIVED AND
FILED

APR 23 1974

JOHN LIVEIRA, County Clerk

CORNER RESTORATION


By *Barbara Lemon* Deputy

CORNER East $\frac{1}{4}$ Sec. 26 TWP 13S RANGE 29 E., W.M.

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:

North between secs. 25 & 26.

40.00 Set stone 16x10x10 for $\frac{1}{4}$ sec. cor.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1953
ROBERT D. BAGETT
598

April 17, 1974

Grant County Surveyor

EVIDENCE FOUND:

Found basalt stone 16x10x5 mkd. $\frac{1}{4}$ in rock jack of fences running north - south - and east from this rockjack. I accept this position as being the location of the original corner based upon the evidence found and the harmonious relationship to other known corners in the area.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set a 1 $\frac{1}{2}$ "x30" iron pipe, 24" in the ground with brass cap mkd. as shown,
from which NEW BEARING TREE: MONUMENT MARKED

A juniper 6 ins. in diam., bears N.62°E., 169.8 ft., mkd.
 $\frac{1}{4}$ S25 CS BT. (tagged with Co. Sur. BT tag)

A juniper fence post at the corner of fences running
N-S- & E, bears S45°E., 0.5 ft. (tagged with CS Bt tag.)

Set orig cor. stone North & along side iron pipe.
Used steel tape and compass, 20°E. var.

Complete and File with Office of the Grant County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

Measured to face of
BT.

