


CERTIFIED RECORD OF LAND CORNER MONUMENTATION
C1/4 Section 18, T13S, R30E, W.M.

History of original corner establishment:
NONE



Description of corner evidence found:
NONE



See Map of Survey No. 1722

Description of monument and accessories set at corner location:

At the corner position determined by survey I set a 5/8" x30" iron pin with attached 2" aluminum cap, 20 inches in ground, built mound of stone around cap. The cap is stamped as shown in the diagram.

From which:

- A 5/8"x30" iron pin bears N67°E, 37.30 feet, with attached red plastic cap marked CORNERSTONE SURVEYING INC.
- A 5/8"x30" iron pin bears S23°E, 19.81 feet, with attached red plastic cap marked CORNERSTONE SURVEYING INC.
- A 5/8"x30" iron pin bears S31°W, 61.43 feet, with attached red plastic cap marked CORNERSTONE SURVEYING INC.
- A 5/8"x30" iron pin bears N23°W, 16.81 feet, with attached red plastic cap marked CORNERSTONE SURVEYING INC.

The bearings are based on Survey No. 1722 and I used an EDM to tie references.

Date: November 16, 2004

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 22 day of Dec, 2004.
Robert D. Boyer by _____
(COUNTY OFFICIAL) (DEPUTY)