


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Original corner established by: John B. David , Deputy Surveyor, under Contract No. 331, dated June 8, 1869.

Surveyor General Record States: Set stone 14x9x7 for 1/4 section corner.



Description of corner evidence found:

No evidence of the original corner was found.



See Record Map of Survey No. 1700

Description of monument and accessories set at corner location:

At the position determined by proportion, I set a 2½"x30" aluminum pipe with attached 3½" aluminum cap, 16 inches in the ground, surrounded by a mound of stone. The cap is stamped as shown in the diagram.

From which:

- A 15" Juniper bears N27°E, 21.0 feet, marked 1/4S5BT.
- A 9" Juniper bears S34°E, 29.7 feet, marked 1/4S5BT.
- A 9" Juniper bears S62°W, 12.8 feet, marked 1/4S6BT.
- A 8" Juniper bears N41°W, 23.2 feet, marked 1/4S6BT.

I used a steel tape measuring to a 50d nail driven in the side center at the root crown of the BT's and magnetic compass, with 18° E. declination.

Date: April 22, 2004

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 3 day of May, 2004.
Robert D. Bogan by _____
(COUNTY OFFICIAL) (DEPUTY)