


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Original corner established by: John B. David , Deputy Surveyor,
under Contract No. 331, dated June 8, 1869.

Surveyor General Record States: Set stone 14x10x7 for 1/4 section
corner.



Description of corner evidence found:

Found stone 13x10x5 inches, lying flat, marked 1/4. An east-west
fence line is 3 feet north of the corner.



See Record Map of Survey No. 1700

Description of monument and accessories set at corner location:

I accept the marked corner stone position for this corner. I set a 2½"x30" aluminum pipe with
attached 3½" aluminum cap, 14 inches in the ground, surrounded by a mound of stone. Placed
original marked stone north alongside pipe. The cap is stamped as shown in the diagram.

From which:

A 5/8"x30" iron pin bears N66°E, 8.24 feet, with attached red plastic cap
marked CORNERSTONE SURVEYING INC.

A 5/8"x30" iron pin bears S62°E, 9.96 feet, with attached red plastic cap
marked CORNERSTONE SURVEYING INC.

A 5/8"x30" iron pin bears S61°W, 10.56 feet, with attached red plastic cap
marked CORNERSTONE SURVEYING INC.

A 5/8"x30" iron pin bears N58°W, 25.47 feet, with attached red plastic cap
marked CORNERSTONE SURVEYING INC.

I used a steel tape and magnetic compass, with 20° E. declination, to tie references.

Date: April 20, 2004

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 3 day of May, 2004.
Robert O. Sargent by _____
(COUNTY OFFICIAL) (DEPUTY)