


CORNER RESTORATION

CORNER N $\frac{1}{4}$ S-21 TWP 13S RANGE 31E

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: #131

CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:

Set stone 15"x12"x8"

RESTORATION BY, STAMP AND DATE:

May 19, 1970



EVIDENCE FOUND:

Found stone 15"x12"x8" Mkd. $\frac{1}{4}$ in old fence corner

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 1"x30" iron post with BC Mkd.

From which:

- A juniper 14" diameter bears S80E, 23.6 ft.
Mkd. $\frac{1}{4}$ S-21 BT
- A juniper 10" diameter bears N30W, 77.0 ft.
Mkd. $\frac{1}{4}$ S-16 BT

MONUMENT MARKED

Grant County Surveyor

T13S R31E

S-16
 $\frac{1}{4}$ -----
S-21
1970

LS 644

Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon, Compass & Steel Tape
Courthouse, Canyon City, Oregon 97820

N-11