

CORNER RESTORATION

CORNER: NW SEC. 22 TWP. 13 S. RANGE 31 E., W.M.


ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869

SUBSEQUENT SURVEYS:

- Remonumented by Robert Bagett, County Surveyor in 1981.
See Corner Restoration Records.



ORIGINAL DESCRIPTION: Set Stone 16x10x8 for corner to Secs. 15, 16, 21 and 22.

- Bagett found the original stone in 1981. Bagett's record states: I set a 1½" x30" iron pipe 28 inches in the ground with brass cap marked as shown. From which I scribe NEW BEARING TREES:
A Juniper 7 inches in diam. bears N.35°E., 80.5 ft. mkd. T13SR31ES15 CSBT.
A Juniper 10 inches in diam. bears S.40°E., 68.5 ft. mkd. T13SR31ES22 CSBT.
A Juniper 8 inches in diam. bears S.26°W., 64.0 ft. mkd. T13SR31ES21 CSBT.
A Juniper 10 inches in diam. bears N.34°W., 63.6 ft. mkd. T13SR31ES16 CSBT.

RESTORATION BY, STAMP AND DATE:


J.L. Hatfield, PLS

RECEIVED AND
FILED

March 19, 2010

OFFICE OF COUNTY SURVEYOR

ATTEST:



OREGON
NOVEMBER 30, 2007
JASON L. HATFIELD
#69454


EXPIRES: 6/30/2011

March 1, 2010

Grant County Surveyor (Deputy)

EVIDENCE FOUND: Found a 1½" iron pipe with attached 2½" brass cap attached, marked as shown below, set in a mound of stone. The monument is in good condition. I found all four BT's, which were alive and healthy, with partially healed blazes. The BT tags were no longer attached to the SE and SW bearing trees.

I attached new BT tags to the trees.



STATE PLANE COORDINATES (3601 OR N)

Reference Datum: NAD83

Northing: 282,852.89 ft.

Easting: 8,598,745.27 ft.

Ellip. Ht: 3,194.7 ft.