


CORNER RESTORATION

CORNER N¹/₄ S-22 TWP 13S RANGE 31E
ORIGINAL SURVEY BY: John B. David
CONTRACT NUMBER: #131
CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:
Set stone 21"x12"x10"


RESTORATION BY, STAMP AND DATE:
May 19, 1970



EVIDENCE FOUND:
Found Stone 24"x12"x10" mkd. 1/4 in a mound of stone

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.
Set 1"x30" iron post with BCmkd.
From which:
A juniper 6" diameter bears S19E, 29.9 ft.
mkd. 1/4 S-22 BT
A juniper 8" diameter bears N15E, 58.6 ft.
mkd. 1/4 S-15 BT



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon, Compass & Steel Tape
Courthouse, Canyon City, Oregon 97820