

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index No. P-7

History of original corner establishment:
Set by survey.

DIAGRAM

T13S R31E
C1/4 S20 BT
1994
PLS 2632

Description of corner evidence found:
Nothing found. Set by survey.


Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 1"x30" iron pipe with a 2.375" brass cap stamped as shown on the DIAGRAM, 18" in the ground, with a mound of stone and earth around cap.

From which:

A 14" juniper, bears: S50°17'03"W, 63.21 ft., scribed C1/4 S20 BT
A 16" juniper, bears: S30°59'14"E, 40.21 ft., scribed C1/4 S20 BT
A 6" juniper, bears: S88°46'07"W, 49.62 ft., scribed C1/4 S20 BT
A 5/8"x30" rebar with plastic cap, bears: N71°03'19"E, 291.7 ft.

Measurements to BT's were taken with an EDM with bearings based on the survey control network. Nailed a stainless steel washer stamped PLS 2632 on blaze as taken this survey.



This work was performed by:
Carl J. Stout PLS 2632
Witnessed by: James Hancock
May 28, 1994
Refer to Grant Co. Survey No.: 1322

Renewal Date: 12/31/94

Office of Surveyor County of Grant

State of Oregon, I hereby certify that the within instrument was filed in this office for

record on the 22 day of Sept, 19 94.

Robert D. Bageot by _____
(County Official) (Deputy)