

RECEIVED AND
FILED

SEP 7 1973

CORNER RESTORATION

JOHN LIVEIRA, County Clerk

Barlene Lemon

By		Deputy	

W. $\frac{1}{4}$ Cor.
Sec. 21 TWP 13 S., RANGE 31 E., W.M.

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869

WC

21

ORIGINAL DESCRIPTION:

North between secs. 20 and 21.

Var. $20^{\circ}30'$ East.

37.50 John Day River, 60 lks. wide, runs West.

40.00 Set Stone 16x8x7 for $\frac{1}{4}$ sec. cor.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

August 8, 1973

Grant County Surveyor

EVIDENCE FOUND: SEE MAP OF SURVEY NO. 310.

The original $\frac{1}{4}$ corner stone was not found. This area has been dredged extensively for gold. The $\frac{1}{4}$ corner was probably destroyed in such an operation.

The position of the $\frac{1}{4}$ cor. was established by means of single proportionate measure between the accepted section corners North and South $\frac{1}{2}$ mile. The corner point falls in the John Day River, I therefore set a Witness Corner on the section line 65.00 feet South, described below.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At point for Witness Corner: Set a $1\frac{1}{2}$ "x30" iron pipe 26 inches in the ground with brass cap marked as shown: MONUMENT MARKED
from which NEW BEARING TREES:

- A 7" cottonwood bears $S59^{\circ}E$, 54.6 ft., mkd.,
 $\frac{1}{4}$ S21 WC CS BT.
- A 8" cottonwood bears $S2^{\circ}W$, 66.0 ft., mkd.,
 $\frac{1}{4}$ S20 WC CS BT.

I tagged both BTs with County Surveyor BT signs.
Raised a mound of stone, 3 ft. base to top of pipe.
Used compass, 20° E. variation and steel tape, measuring to face of blaze on BTs.
Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

