

RECEIVED AND
FILED

FEB 28 1973
JOHN LIVEIRA, County Clerk

CORNER RESTORATION


By _____ Deputy

SW cor.
CORNER Sec. 21 TWP 13S., RANGE 31 E., W.M.

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:

North between secs. 28 & 29. Va. 21° East,

40.00 Set Stone 14x8x6 for $\frac{1}{4}$ sec. cor.

80.00 Set stone 18x14x9 for corner to secs. 20, 21, 28, & 29.

RESTORATION BY, STAMP AND DATE:

February 8, 1973

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

EVIDENCE FOUND:

The original section corner was not found. A steel fence post has been driven into the ground, projecting about 14 inches above ground level. This has been used as the section corner for years and is in harmonious relationship with other known corners in the area. I therefore accept its position as the true section corner.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

I removed the $4\frac{1}{2}$ ft. steel fence post and in its place I set a $1\frac{1}{2}$ "x30" iron pipe, 27 inches in the ground with brass cap marked as shown. I buried several good sized stones with the pipe. **MONUMENT MARKED**

From which, NEW ACCESSORIES:

An unmarked juniper 12" diam., bears N. 49° E, 76.8 ft.

The SW corner of P.N. Shown's house bears N. 80° E., 79.2 ft.

An unmarked, schoolmarm'd, juniper, 10" base bears S. 57° W., 48.7 feet.

Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

Steel tape & compass
with 20° E. var.
Measurements are to the face
of the trees.

