

RECEIVED AND
FILED

JUN 14 1973

JOHN LIVEIRA, County Clerk

By *Robert D. Baggett* Deputy

CORNER RESTORATION


SE Cor.

CORNER Sec. 29 TWP 13 S., RANGE 31 E. m W.M.

ORIGINAL SURVEY BY: Thompson, Pengra, and David

CONTRACT NUMBER: 131



CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:

80.00 Set stone 18x9x5 for corner to secs. 28, 29, 32, 33.

RESTORATION BY, STAMP AND DATE:



April 23, 1973

EVIDENCE FOUND:

Found a basalt stone 18x10x7 inches marked with 4 grooves on the East side and 1 groove on the South side. This stone was set in a mound of stone.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point I set a 1 1/2" x 30" iron pipe, 20 inches in the ground with brass cap marked as shown. Set the original stone North and alongside the iron pipe. FROM WHICH NEW BEARING TREES: MONUMENT MARKED

- A 17" juniper bears N74°E, 37.5 feet, mkd. T13SR31E S28 CS BT.
- A 6" juniper, in fenceline, bears S5°E., 23.0 ft., marked S33 CS BT.
- A 8" juniper bears S82°W., 33.3 ft., marked T13SR31E S32 CS BT.
- A 8" juniper bears N60°W., 67.7 ft., mkd. S29 CS BT.

Complete and File with Office of the Grant Used compass, Var.

County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

20° East. Steel tape
Measurements are to the
face of the blaze on the BTs.

