


CORNER RESTORATION

NW Cor.
CORNER Sec. 34 TWP 13 S., RANGE 31 E., W.M.

ORIGINAL SURVEY BY: John B David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:

North between secs. 33 and 34.

80.00 Set stone 20x14x6 for corner to secs. 27, 28, 33, and 34.

RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

JAN 15 1974

JOHN LIVEIRA County Clerk

By Patty Lowrey Deputy

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

December 6, 1973

Grant County Surveyor

EVIDENCE FOUND:

Found dim mound of stone at the corner of fences running North and West, found stone 12x6x15 in rockjack, but could find no marks on it. I accept this position as the section corner based on the fence, the mound, and the harmonious relationship to other known corners in the area.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set a 1 $\frac{1}{2}$ "x30" iron pipe 26" in the ground with brass cap marked as shown.


MONUMENT MARKED

Surround pipe with a mound of stone and raise to top of cap.

No bearing trees available.

SEE MAP OF SURVEY NO. 324

Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820



V-13