


CORNER RESTORATION

N. 1/4 Cor.
CORNER Sec. 34 TWP 13 S., RANGE 31 E., W.M.

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:

S 89° 40' W on a true line between Secs. 27 and 34.

Var 21° East.

39.75 Set stone 1 1/4 x 12 x 10 for 1/4 corner.

RECEIVED AND
FILED

JAN 15 1974

JOHN LIVEIRA, County Clerk

By *Betty Lowery* Deputy

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

December 6, 1973

Grant County Surveyor

EVIDENCE FOUND: SEE MAP OF SURVEY NO. 324.

The original 1/4 corner stone was not found.

The position of the 1/4 corner was established by means of single proportionate measure between the accepted section corners 1/2 mile East and West.


DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At point for 1/4 section corner: Set a 1 1/2" x 30" iron pipe 2 1/4 inches in the ground, with a brass cap marked as shown: MONUMENT MARKED

Raised a mound of rock to the top of the pipe.

No suitable bearing trees available.



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820