

RECEIVED
FILE

JUL 30 1973

JOHN LIVEIRA, County Clerk

By _____ Deputy


CORNER RESTORATION

W $\frac{1}{4}$ cor.
CORNER Sec. 33 TWP 13S RANGE 31E., W.M.

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:

North between sections 32 & 33.
40.00 Set stone 16x9x6 for $\frac{1}{4}$ sec. cor.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

July 7, 1973

Grant County Surveyor

EVIDENCE FOUND:

The original $\frac{1}{4}$ corner stone was not found, nor was any evidence of the original corner found.

I therefore establish the $\frac{1}{4}$ cor. by means of single proportionate measure between section corners north and south of this $\frac{1}{4}$ cor.

This corner falls about 250 feet East of a N-S fenceline.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set a $1\frac{1}{2}$ "x30" iron pipe 28" in the ground with brass cap marked as shown.

from which I scribe NEW BEARING TREES:

A juniper, 12" diam., bears S1°E, 3.4 ft., mkd. $\frac{1}{4}$ S33 CS BT.

A juniper, 12" diam., bears S66°W, 17.8 ft., mkd. $\frac{1}{4}$ S32 CS BT.

I tagged both BTs with County Surveyor BT tags.

I imported several large stones and surrounded the iron pipe with them.

Used a compass with 20° E. var. and a steel tape, measuring to the face of the blaze on the BTs.

Complete and File with Office of the Grant

County Surveyor, Grant County, Oregon,

Courthouse, Canyon City, Oregon 97820

