


# CORNER RESTORATION

CORNER: C-E1/16 SEC.35 TWP. 13S. RANGE 31E.

ORIGINAL SURVEY BY: CORNER NOT

CONTRACT NUMBER: PREVIOUSLY ESTABLISHED

CONTRACT DATE:



ORIGINAL DESCRIPTION: None

RESTORATION BY, STAMP AND DATE:

M.C. Springer, PLS  
J.L. Hatfield, LSIT

RECEIVED AND  
FILED

APRIL 12, 2007  
OFFICE OF COUNTY SURVEYOR  
*Robert D. Baggett*  
ATTEST: *James L. Hatfield*



March 5, 2007

EVIDENCE FOUND: None

See Record Land Partition No. 2007-06

## DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings including compass var.

At the corner point: I set a 5/8"x 30" iron pin, 30" in the ground, with attached 1½" alum. cap marked as shown.

From which I SET NEW REFERENCE POINTS:

A 5/8"x 30" iron pin, bears N58°E, 25.8 ft., with attached 1½" alum. cap marked BGB SURVEY MARKER RP 1 2007

A 5/8"x 30" iron pin, bears S27°E, 25.9 ft., with attached 1½" alum. cap marked BGB SURVEY MARKER RP 2 2007



Used mag. compass with 17°E var. and steel tape to measure reference points.