


RECORD OF LAND CORNER MONUMENTATION

CORNER: E1/16 Cor. S. Line Sec. 34 (only) T.13S., R.31E., W.M.

ORIGINAL SURVEY BY: CORNER

CONTRACT NUMBER: NOT PREVIOUSLY

CONTRACT DATE: ESTABLISHED



ORIGINAL G.L.O. DESCRIPTION: None. Corner not previously established

EVIDENCE FOUND: None. Corner not previously established

DESCRIPTION OF MONUMENT AND ACCESSORIES SET:


At the corner point, we set a 5/8"X30" iron pin with attached 2 1/2" aluminum cap, 29" in the ground. Cap is marked as shown below.

FROM WHICH, I SET THE FOLLOWING REFERENCE POINT:

A 5/8"X30" iron pin with attached yellow plastic cap marked
BENCHMARK SURVEYING bears N.48°12'E., 22.97 ft.,

ALSO:

A 5/8" iron pin with attached yellow plastic cap marked BGB
SURVEY MARKER Bears S.89°58'W., 107.42 ft.



Used RTK GPS to measure Reference Points. Bearings to RP's are based on Grant County Record Map of Survey No. 2161

RESTORATION BY:


Michael C. Springer, PLS
Nick N. Springer, Survey Tech.

Benchmark Land Surveying, Inc.
217 N. Canyon Blvd.
John Day, OR, 97845
(541) 575-1251
benchmarkls.com


Surveyed: June 24, 2021

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

JUN 25 2021

BY: 

REGISTERED
PROFESSIONAL
LAND SURVEYOR


OREGON
JULY 9, 2002
MICHAEL C. SPRINGER
#70918

EXPIRES: 6/30/2022