


CORNER RESTORATION

N $\frac{1}{4}$ Sec. cor.
CORNER Sec. 35 TWP 13S RANGE 32E

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869





ORIGINAL DESCRIPTION:

West on a true line between Secs. 26 & 35.

40.00 set stone 16x8x8 for $\frac{1}{4}$ sec. corner.

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
S. F. Jackson
S. L. Crane



March 22, 1978

Grant County Surveyor

EVIDENCE FOUND:

Found stone 15"x8"x9" marked $\frac{1}{4}$.

See Map of Survey No. 502

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set 1 $\frac{1}{2}$ "x30" iron pipe 26" in the ground with brass cap marked as shown.

MONUMENT MARKED


Buried original corner stone East and alongside iron pipe.

Surrounded pipe with a mound of stone.

No BT's available.

An existing fence corner ^{with fences} running South and East is southerly 60' from corner point.

Also, an existing fence corner ^{with fences} running South and West is southerly 80' from corner point.



RECEIVED AND
FILED

APR 25 1978

JOHN LIVEIRA, County Clerk

By Dominic Laurone Deputy

V-19