


## CORNER RESTORATION

CORNER NE cor 29 TWP 13 S RANGE R33 E

ORIGINAL SURVEY BY: JOHN B. DAVID

CONTRACT NUMBER: 131

CONTRACT DATE: JUNE 8, 1869



**ORIGINAL DESCRIPTION:**

Set stone 16 x 10 x 9 for corner to Sections 20, 21, 28, and 29.

**RESTORATION BY, STAMP AND DATE:**

OREGON EAST ENGINEERING, INC  
P. O. BOX 277  
MT. VERNON, OREGON

NOVEMBER, 1977

**RECEIVED AND FILED**

NOV 25 1977

*John Liveira*  
**JOHN LIVEIRA, County Clerk**

By \_\_\_\_\_ Deputy

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Douglas M. Ferguson*  
OREGON  
JULY 12, 1968  
DOUGLAS M. FERGUSON  
848

**EVIDENCE FOUND:**

Found original 16 x 10 x 9 stone with faintly visible markings in a circle of stones. Position was accepted due to its harmony with other found corners.


**DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:**

Show how trees are scribed and basis of bearings, including compass var.

Set a 2 1/2" x 30" galvanized iron pipe and brass cap marked as shown in the ground. Raised a mound of stones up around the pipe. No bearing trees were available.

Compass variation 20° E.

**MONUMENT MARKED**



Complete and File with Office of the Grant  
County Surveyor, Grant County, Oregon,  
Courthouse, Canyon City, Oregon 97820